## NORTHSTAR CHRYSLER INC. SERVICE HISTORY REPORT **Detailed Report**

From 01/01/2007 To 07/06/2021 S1 - Shop 1 - LACRETE

07/06/2021

Page: 1

S1 - Shop 1 - LACRETE SHOP Veh: 2008 DODGE CALIBER VIN: <u>1B3HB68F18D735584</u> Odom Out: 146416 Lic: C: \$5,418.26 10/17/16 SO: <u>L15478</u> Email: REPLACE LONG BLOCK ON 2007 2.4L CALIBER AS PER REQUEST Replaced 2.4L Long Block. OP Code Price Code CRO 259 Tech Veh: 2008 DODGE CALIBER VIN: <u>IB3HB68F18D735584</u> Odom Out: 166437 Lic: C: \$853.22 SO: 116948 05/26/17 Email: REPLACE RELEASE BEARING/ACTUATOR Replace clutch slave cylinder/release bearing OP Code 6 Price Code CRO 259 Tech Veh: 2008 DODGE CALIBER VIN: 1B3HB68F18D735584 Odom Out: 180839 Lic: C: \$68.79 SO: 118998 06/02/18 Email: DIAG & REPAIR FOR OIL LEAK FROM BACK OF ENGINE. CUSTOMER REPORTS IT LEAKS MORE WHEN WARMED UP REPLACED GASKET OP Code CRO Price Code Tech 317

> Veh: 2008 DODGE CALIBER VIN: 1B3HB68F18D735584

Lic:

Odom Out: 146617

**∕**11/10/16

SO: 115676

C: \$115.94

Email:

Diagnose for engine losing power when warm, dash lights come one, car works again after cool down

OP Code

Found Vacuum Leak From Breather Hose, Replaced Brittle Hose, Cleared Codes, Repair

## NORTHSTAR CHRYSLER INC. SERVICE HISTORY REPORT

## Detailed Report From 01/01/2007 To 07/06/2021 S1 - Shop 1 - LACRETE

07/06/2021

Page: 2

			Complete.		
	Price Code	CRO			
	Tech	259	h nurvor i i i i i i i i i i i i i i i i i i i		The state of the s
	<del>-</del>			Veh; 2008 DOD	GE CALIBER
				VIN: <u>1B3HB68F</u>	
			C:	Lie:	Odom Out: 152403
12/31/1	6	SO: <u>116023</u>	\$99.20		
Email: PERFC	RM SYNTHE	TIC PENTASTAR OIL	AND FILTER CHANGE. PERFORM 16 S PRESSURES IF NEEDED.		
POINT	OP Code	ILOFPS	Changed Engine Oil and Filter.		
	Price Code	CRO			
	Tech	317		- J > - Lopin Al-Aberral Making IV ( pun Verrennerer	NASAN - POTENTIAL PROPERTY AND STATE TO STATE THE STATE
	Colombia (Colombia Colombia)				
				Veh: 2008 DOD	GE CALIBER
				VIN: <u>1B3HB68</u> F	
			C:	Lie:	Odom Out: 158946
03/23/1		SO: <u>116515</u>	\$458.51		
Email:		TIC PENTASTAR OII	AND FILTER CHANGE. PERFORM 16		
POINT	INSPECTION	AND ADJUST TIRE	S PRESSURES IF NEEDED.		
	OP Code	ILOFPS	Changed Engine Oil and Filter.		
	Price Code	CRO			
	Tech	259			The state of the s
Install	rear bumper va	lence			
	OP Code	13200501	Fascia, rear bumper - Replace One piece (B)		
	Price Code	CRO			
	Tech	259		AMALIAN MENTAL II COMMON PORTO	taaliida daadaa ka tiinka haka tiinka ka daadaa ka k
		ORT FOR A TICKING METHING WITH TH	NOISE WHEN IDLING - CUSTOMER		
avart	OP Code	21	Possible Release Bearing Making Noise,		
	Price Code	CRO			
	Tech	259		and a labour on the same of	
	=			Veh: 2008 DOD	
				VIN: 1B3HB68F	
.= /445.1	15	PO. 114915	C:	Lie:	Odom Out: 164064
u5/09/	1.7	SO: <u>116845</u>	\$153.15		

## NORTHSTAR CHRYSLER INC. SERVICE HISTORY REPORT Detailed Report From 01/01/2007 To 07/06/2021 S1 - Shop 1 - LACRETE

07/06/2021

Page: 3

Email: MOUNT AND BALAN	NCE TIRES AS PE	R REQUEST
OP Code	22	Mounted and Balanced Rims and Tires.
Price Code	CRO	
Tech	317	
AND AND THE PARTY OF THE PARTY	METER METERS AND COLUMN STATEMENT OF THE POSSESSION STREET, AND ST	

Total Service Orders: \$7,167.07